

Technical Manual Index

CT7 TURBOSHAFT

CT7-2A/-2D/-2D1/-6/-6A/-8/-8A/-8A5/-8B/-8B5/-8E/-8E5/-8F/-8F5

Component Maintenance Manuals

September 1, 2008

The manuals are listed in publication number order.

The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

90 - - - - - 90 day revision cycle (Quarterly updates)
180 - - - - - 180 day revision cycle (Semi-annual updates)

365 - - - - - 365 day revision cycle (Annual updates)
AR - - - - - As Required revision cycle

Publication Numbers with a (@) symbol in the Publication No. column indicates that the manual is a combined CT7 Turboshaft and Turboprop publication.

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
72-60-00	GEK 108722 formerly in SEI-573	-2/-6 All	Particle Separator Blower	6038T59P02 6038T59P04	T20180-17 T20180-21	Sundstrand Aerospace (99167)	12/1/86	2	10/31/99	AR
73-13-00	GEK 108723 formerly in SEI-573	-2A	Sequence Valve	6044T27G02	-	GE Aircraft Engines (99207)	9/1/86	2	10/31/99	AR
74-22-12	GEK 108724 formerly in SEI-573	-2 All	Electrical Control Unit	4082T38G04 4082T38G07 4076T27G01 4076T27G02	7116M93G04 7116M93G06 7046M95G03 7046M95G04	BAE Systems Controls (89954) formerly Lockheed Martin	6/30/91	2	10/15/01	AR
74-23-00	GEK 108725 formerly in SEI-573	-2 All	Engine History Recorder	4046T26G04	7084M83G02	BAE Systems Controls (89954) formerly Lockheed Martin	11/30/92	1	12/31/99	AR
75-11-00	GEK 108726 formerly in SEI-573	-2 All	Anti-icing Bleed & Start Valve	5044T08P03 5044T08P05 5044T08P10 5044T08P11	73340-10 73340-12 73340-17 73340-18	Vacco Industries (1PVC5)	9/1/86	3	11/30/99	AR
75-31-01	GEK 112188	-8 All	Particle Separator Blower	3062T06P03	4101412B	Hamilton Sundstrand (45153)	3/1/04	-	-	AR

Technical Manual Index

CT7 TURBOSHAFT

Component Maintenance Manuals
September 1, 2008

<u>ATA Number</u>	<u>Publ. Number</u>	<u>Engine Model</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>VIN</u>	<u>OEM Name (Vendor Code)</u>	<u>Basic Issue Date</u>	<u>Rev. No.</u>	<u>Rev. Date</u>	<u>Rev. Cycle</u>
74-20-02	GEK 112189	-8 All	Ignition Leads	3060T08P01 3060T08P02	9059255-1 9059255-2	Unison Industries (59501)	3/1/04	-	-	AR
75-11-01	GEK 112190	-8 All	Anti Ice and Start Bleed Valve	3062T13P02 3062T13P03	C152510-2 C152510-3	Microtechnica (A0076)	5/15/06	1	7/31/07	AR
73-22-33	GEK 112197 (Supplied by Hamilton Sundstrand)	-8 All	Electronic Engine Control	4110T55P26 4110T55P27 4110T55P28 4110T55P29 4110T55P30 4110T55P31 4110T55P32 4110T55P34 4110T55P35 4110T55P36 4110T55P38	819140-7-008 819140-7-007 819140-7-009 819140-4-008 819140-4-009 819140-4-011 819140-7-011 819140-7-010 819140-8-011 819140-8-010 819140-9-010	Hamilton Sundstrand (73030)	6/1/05	-	-	AR
73-20-01	GEK 112198	-8 All	Fuel Metering Unit	4110T52P10	819700-8	Hamilton Sundstrand (73030)	9/15/04	-	-	AR
79-20-07	GEK 112199@	-8 All CT7-9 All	Lube and Scavenge Pump	3065T20P01	31-75107-3026-4	Parker Hannifin Nichols Airborne Division (86329)	8/31/04	-	-	AR
73-20-00	SEI-573	-2A	Hydromechanical Control Unit	6038T62P09 6038T62P11 6038T62P13 6038T62P22 6038T62P24	763700-9 763700-11 763700-13 763700-32 763700-34	Hamilton Sundstrand (73030)	9/1/86	1	11/30/92	AR

Technical Manual Index

CT7 TURBOSHAFT

Component Maintenance Manuals
September 1, 2008

ATA Number	Publ. Number	Engine Model	Nomenclature	Part Number	VIN	OEM Name (Vendor Code)	Basic Issue Date	Rev. No.	Rev. Date	Rev. Cycle
73-10-01 Formerly 73-11-00	SEI-650 @ formerly in SEI-573	-2/-6 All CT7-5/-7/ -9 All	Overspeed and Drain Valve	6044T78G03 6044T78G04	-	GE Aircraft Engines (99207)	9/30/84 (Formerly 9/1/86)	3	4/30/02	AR
79-20-06 formerly 79-22-00	SEI-651@ formerly in SEI-573	-2/-6 All CT7-5/-7/ -9 All	Lube & Scavenge Pump	5034T11P04 5034T11P05	31-75107-3010-4 (GD677-4) 31-75107-3022-4 (GD677-6)	Parker-Hannifin Corp., Nichols Aircraft Div. (86329)	7/15/84 (formerly 9/1/86)	3	6/30/00	AR
73-10-01 formerly 73-12-00	SEI-652 @ formerly in SEI-573	-2/-6/-8 All CT7-5/-7/ -9 All	Fuel Boost Pump	5034T91P06	RR53150F	Crane Co. (Lear Romec Div.) (51663)	9/30/84 (formerly 9/1/86)	4	4/30/00	AR
79-21-01 formerly 79-21-02	SEI-654 @ formerly in SEI-573	-2/-6/-8 All CT7-5/-7/ -9 All	Fuel/Oil Cooler	5034T31P01 5034T31P02 5044T42P02	UA536190-2 UA536190-3 UA537628-3	Parker-Hannifin Corp., Aerospace Div. (78943)	9/30/84 (formerly 9/1/86)	2	6/30/00	AR
79-20-02 formerly 79-21-00	SEI-665 @ formerly in SEI-573	-2/-6/-8 All CT7-5/-7/ -9 All	Fuel Cooled Oil Cooler	6044T95P01 6044T95P02	735551A, 1B 735551C	Hamilton Sundstrand (73030)	9/30/84 (formerly 9/1/86)	3	5/31/00	AR

Questions or comments concerning the content of this index or changes in distribution should be directed to the GE – Aviation Customer Support Center. From within the United States, call toll-free 877-432-3272, FAX 877-432-3329. For International callers, dial 1-513-552-3272, FAX 1-513-552-3329. E-mail address is geae.csc@ae.ge.com.